

Institute/Department: _____

Checklist for Running Luminex in NHLBI Flow Core

- 1) Schedule instrument time with NHLBI Flow Core Facility staff.

Contacts:

Leigh Samsel
samsell@nih.gov

Phil McCoy
mccoyjp@nih.gov

- 2) Prior to scheduled instrument run time, establish protocol in BioPlex Manager software with assistance of NEI core staff. Fill out and utilize Luminex Plan document.
- 3) Bring plate to NHLBI flow core (Building 10, Room 8C104) ready to run on instrument.
- 4) NHLBI Flow core staff will be responsible for starting up and QC'ing instrument.
- 5) Schedule data analysis time with NHLBI flow core facility staff (if desired), or NHLBI core staff will email you data files. **NO FLASH DRIVES ARE PERMITTED ON COMPUTER PER NHLBI IT RULES.**

